

Ao Smith Motors Wiring Diagram And Brake Motor Wiring Diagram By XPMissions

Ao smith motors wiring diagram and brake motor wiring diagram

AO SMITH 56 FRAME WIRING
#1-COMMON
#2-HIGH
#3 or 4-LOW



GREEN WIRE HERE (GROUND)


WHITE WIRE - COMMON

BLACK OR RED - HIGH


BLACK - LOW SPEED OR RED

HIGH & LOW WIRE COLOR DEPENDS ON CONTROL NOT ON THE MOTOR, CONTROL DETERMINES COLOR

VIEW FROM OUTSIDE OF MOTOR AT SWITCH END.



Click to enlarge



	ROTATION FACING LEAD END	L1	L2	JOIN
HIGH VOLT	C.C.W.	T1	T4 T5	T2, T3 T8
	C.W.	T1	T4 T8	T2, T3 T5
LOW VOLT	C.C.W.	T1 T3, T8	T2, T4 T5	
	C.W.	T1, T3 T5	T2, T4 T8	

AD MAY BE WHITE

TOLERANCES UNLESS OTHERWISE SPECIFIED	
DEC.	INCHES
.X	±.1



ELECTRIC MOTORS GEARMOTORS AND DRIVES

DRAWN	JRW	08/27/74
CHK	TEM	
APPD		10/11/74

xpmissions.com